## Oil Field Environmental Incident Summary

**Responsible Party:** CONDOR PETROLEUM, INC. **Well Operator:** CONDOR PETROLEUM, INC.

Well Name: A. B. ERICSON 1-A

Field Name: STONEVIEW Well File #: 5192

Date Incident:10/14/2014Time Incident:11:45Facility ID Number:County:DIVIDETwp:160Rng:95Sec:3Qtr:

Location Description:

Submitted By: Emily Drabbs Received By:

Contact Person: Dave Heilman

216 16TH STREET SUITE 1750

DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building: 1 Mile
Distance Nearest Water Well: 1 Mile

**Barrels** 

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Barrels

Oil 1 Barrels

Other 3 barrels

2

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: 10/6/2015 Clean Up Concluded: 10/15/2014

Risk Evaluation:

n/a

**Brine** 

Areal Extent:

less than 1 barrel of oil spray out onto farmers field

## Potential Environmental Impacts:

n/a

## Action Taken or Planned:

water has been cleaned up and taken to disposal. need to notify farmer. additionally gravel has been spread at location after clean up.

Wastes Disposal Location: Company owned salt water disposal.

Agencies Involved:

## **Updates**

Date: 10/27/2014 Status: Reviewed - Follow-up Required Author: Roberts, Kris

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Release from a valve/piping leak sprayed off location. Followup is necessary.

Date: 10/30/2014 Status: Correspondence Author: Stockdill, Scott

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Contact was made with company.

Phone call regarding cleanup status of spill that occurred on October 14. The company reps did not believe areas off of location were impacted. They were informed that there was a large area that had been sprayed by oil from the well.

More followup is necessary to ensure proper cleanup.

Date: 10/30/2014 Status: Reviewed - Follow-up Required Author: Stockdill, Scott

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Arrived on location 10/30/2014.

No action has been taken by company to clean up spill. Call was made to company contact to check cleanup status.

Followup necessary.